



EQUIPMENT

AFGRI EQUIPMENT AUSTRALIA PTY LTD
Trading as AFGRI
ABN: 52 008 686 002 ACN: 008 686 002
Refrigerant Trading Authority: AU29549
MRB: 1826
MD: 19390
www.afgri.com.au

*** DOCUMENT COPY ***

SERVICE ESTIMATE #558350

Customer Name & Address:
Viridis Ag Pty Ltd - Yupiri Farm
Yupiri
suite 3Level 3, Swift Street,
ALBURY NSW 2640

Driver Name & Address:
- Viridis Ag Pty Ltd - Yupiri Farm
Yupiri
RMB 14364
ESPERANCE WA 6450

Branch: ES
Expiry Date: 11/01/2025
Document Date: 12/12/2024
Rego No.: 233543
Stock No:
Make: JOHN DEERE
Model: S790
Vehicle ID No.: 1Z0S790APKF116802
Odometer:
Page: 1 of 4

Code	Type	Detail	Value
05	R	PRE SEASON HEADER REPAIRS SERVICE ESTIMATE	

		1.Engine oil, oil filters, fuel filters, hydraulic filters, air filters and cab filters	
		2.Tension all belts and chains.	
		3.Update software	
		4.Run up and check over including oiling chains	
		5.Test grain lose monitors	
		6.Fit correct pins to chopper actuators	
		7.Fit correct tensioner set up to chopper drive belt tensioner	
		8.Replace cleaning fan belt	
		9.Replace the reverser box drive belt (feeder house LH belt) + fit nut that is missing for mounting bracket	
		10.Replace feeder house drive chain + idler sprockets x2	
		11.Replace chaffer spreader supply and return pipes (rubbed together showing wire)	
		12.Remove half link from feeder house chains and set correct tension	
		13.Replace leaking couplers on multi dock (Bottom LH & RH)	
		14.Replace the pan drive belt on RH side	
		15.Investigate grain loss monitor codes	
		16.Tighten jam nut retaining hydraulic return manifold	
		17.Replace chaff spreader board (may require more parts once stripped down)	

ESPERANCE 6450
Phone: 08 9071 6702 Fax: 08 9071 3887
Email: esperanceservice@afgri.com.au
87 Norseman Road
ESPERANCE WA

BANK DETAILS
Bank: NAB
Branch: PERTH
BSB: 086006 Account No: 721315336
Account Name: AFGRI Equipment Australia

Part of the AFGRI Group of Companies





EQUIPMENT

AFGRI EQUIPMENT AUSTRALIA PTY LTD
Trading as AFGRI
ABN: 52 008 686 002 ACN: 008 686 002
Refrigerant Trading Authority: AU29549
MRB: 1826
MD: 19390
www.afgri.com.au

*** DOCUMENT COPY ***

SERVICE ESTIMATE #558350

Customer Name & Address:
Viridis Ag Pty Ltd - Yupiri Farm
Yupiri
suite 3Level 3, Swift Street,
ALBURY NSW 2640

Driver Name & Address:
- Viridis Ag Pty Ltd - Yupiri Farm
Yupiri
RMB 14364
ESPERANCE WA 6450

Branch: ES
Expiry Date: 11/01/2025
Document Date: 12/12/2024
Rego No.: 233543
Stock No:
Make: JOHN DEERE
Model: S790
Vehicle ID No.: 1Z0S790APKF116802
Odometer:
Page: 2 of 4

Code	Type	Detail	Value																								
		18.Replace chopper side sheet as been repaired including chopper bearings (may require more parts once stripped down)																									
		19.Turn chopper blades to fresh side																									
		20.Replace LH chaff spinner bottom bearing support																									
		21.Tighten LH and RH tray auger drive gears																									
		22.Replace rotary screen inner drive belt and cross shaft bearings																									
		23.Replace radiator impellor bearings and blow out the radiator fully																									
		24.Clean out pre cleaner behind fan (partially blocked)																									
		25.Replace clean grain elevator tensioner pulley																									
		26.Replace tailings thresher drive chain idler sprockets																									
		27.Remove clean grain elevator half link																									
		28.Replace both feeder house ram seals (drops overnight a lot)																									
		29.Replace rear wear strips on feeder house chains																									
		30.Inspect bottom sieves and shoe once chopper is removed due to not being able to lift chopper out the way																									
80	R	PARTS REQUIRED																									
		<table><tr><th>Part Number</th><th>Part Description</th><th>Quantity</th><th>Total Cost</th></tr><tr><td>AXE23133</td><td>Idler Sprocket</td><td>2.00</td><td>\$205.94</td></tr><tr><td>AH220916</td><td>Pulley</td><td>1.00</td><td>\$314.21</td></tr><tr><td>AXE60983</td><td>Hydr. Quick Coupler Socket</td><td>2.00</td><td>\$643.02</td></tr><tr><td>AHC11572</td><td>Hydraulic Cylinder Kit</td><td>2.00</td><td>\$340.66</td></tr><tr><td>AHC20488</td><td>Hydraulic Cylinder Kit</td><td>2.00</td><td>\$371.62</td></tr></table>	Part Number	Part Description	Quantity	Total Cost	AXE23133	Idler Sprocket	2.00	\$205.94	AH220916	Pulley	1.00	\$314.21	AXE60983	Hydr. Quick Coupler Socket	2.00	\$643.02	AHC11572	Hydraulic Cylinder Kit	2.00	\$340.66	AHC20488	Hydraulic Cylinder Kit	2.00	\$371.62	\$24,402.14
Part Number	Part Description	Quantity	Total Cost																								
AXE23133	Idler Sprocket	2.00	\$205.94																								
AH220916	Pulley	1.00	\$314.21																								
AXE60983	Hydr. Quick Coupler Socket	2.00	\$643.02																								
AHC11572	Hydraulic Cylinder Kit	2.00	\$340.66																								
AHC20488	Hydraulic Cylinder Kit	2.00	\$371.62																								

ESPERANCE 6450
Phone: 08 9071 6702 Fax: 08 9071 3887
Email: esperanceservice@afgri.com.au
87 Norseman Road
ESPERANCE WA

BANK DETAILS
Bank: NAB
Branch: PERTH
BSB: 086006 Account No: 721315336
Account Name: AFGRI Equipment Australia

Part of the AFGRI Group of Companies





EQUIPMENT

AFGRI EQUIPMENT AUSTRALIA PTY LTD
Trading as AFGRI
ABN: 52 008 686 002 ACN: 008 686 002
Refrigerant Trading Authority: AU29549
MRB: 1826
MD: 19390
www.afgri.com.au

*** DOCUMENT COPY ***

SERVICE ESTIMATE #558350

Customer Name & Address:
Viridis Ag Pty Ltd - Yupiri Farm
Yupiri
suite 3Level 3, Swift Street,
ALBURY NSW 2640

Driver Name & Address:
- Viridis Ag Pty Ltd - Yupiri Farm
Yupiri
RMB 14364
ESPERANCE WA 6450

Branch: ES
Expiry Date: 11/01/2025
Document Date: 12/12/2024
Rego No.: 233543
Stock No:
Make: JOHN DEERE
Model: S790
Vehicle ID No.: 1Z0S790APKF116802
Odometer:
Page: 3 of 4

Code	Type	Detail		Value
JD29980		Needle Bearing	2.00	\$24.24
H171960		Strip	4.00	\$207.88
AXE19940		Idler Sprocket	2.00	\$163.50
AXE72710		Link Chain	1.00	\$303.10
14M7299		NUT HEX FL 12mm ID	1.00	\$3.63
HXE50398		V-Belt	1.00	\$1,192.03
HXE99294		V-BELT	1.00	\$247.26
HXE102288		V-Belt	1.00	\$1,202.15
24M7102		WASHER RH 13.5mm X 44mm	1.00	\$5.56
HXE13552		Compression Spring	1.00	\$58.25
HXE13566		Gauge	1.00	\$55.67
H170141		Pivot	1.00	\$36.36
AXE55766		Belt Tensioner	1.00	\$136.68
AXE36329		Hydraulic Hose	1.00	\$787.02
AXE36333		Hydraulic Hose	1.00	\$323.65
HXE32924		Bracket	2.00	\$343.12
AXE85962		Side Wall	1.00	\$934.45
AXE86038		Side Wall	1.00	\$931.50
AXE85961		Support	1.00	\$10,159.30
AXE21964		Sheet	2.00	\$703.62
HXE30222		Set Screw	2.00	\$15.84
HXE59257		Tone Wheel	1.00	\$597.41
AXE12177		Bearing	2.00	\$553.80
M40461		Pin	2.00	\$3.86
HXE38005		Bushing	2.00	\$78.98

ESPERANCE 6450
Phone: 08 9071 6702 Fax: 08 9071 3887
Email: esperanceservice@afgri.com.au
87 Norseman Road
ESPERANCE WA

BANK DETAILS
Bank: NAB
Branch: PERTH
BSB: 086006 Account No: 721315336
Account Name: AFGRI Equipment Australia

Part of the AFGRI Group of Companies





EQUIPMENT

AFGRI EQUIPMENT AUSTRALIA PTY LTD
Trading as AFGRI
ABN: 52 008 686 002 ACN: 008 686 002
Refrigerant Trading Authority: AU29549
MRB: 1826
MD: 19390
www.afgri.com.au

*** DOCUMENT COPY ***

SERVICE ESTIMATE #558350

Customer Name & Address:
Viridis Ag Pty Ltd - Yupiri Farm
Yupiri
suite 3Level 3, Swift Street,
ALBURY NSW 2640

Driver Name & Address:
- Viridis Ag Pty Ltd - Yupiri Farm
Yupiri
RMB 14364
ESPERANCE WA 6450

Branch: ES
Expiry Date: 11/01/2025
Document Date: 12/12/2024
Rego No.: 233543
Stock No:
Make: JOHN DEERE
Model: S790
Vehicle ID No.: 1Z0S790APKF116802
Odometer:
Page: 4 of 4

Code	Type	Detail	Value	
24M7111		WASHER RH 13mm X 25mm	2.00	\$4.04
HXE18837		Pin Fastener	2.00	\$39.06
AXE70445		Side Wall	1.00	\$1,721.01
HXE93567		Ball Bearing	2.00	\$159.12
AZ10044		Eccentric Locking Collar	2.00	\$27.42
H238867		V-Belt	1.00	\$57.18
FREIGHT		Freight & Handling	1.00	\$1,450.00
81	R	LABOUR		\$14,800.00
		*More parts and labour may be required with in time due to extensive chopper damage that could not be thoroughly inspected.		
82	R	WORKSHOP CONSUMABLES		\$150.00
83	R	*****		
		Repairs completed before the 31st March 2025 are eligible for a 10% discount on parts when installed by AFGRI technicians		

INSPECTED

Service Advisor:

Sub Total: \$39,352.14
GST: \$3,935.21
Total (Inc GST): \$43,287.35

ESPERANCE 6450
Phone: 08 9071 6702 Fax: 08 9071 3887
Email: esperanceservice@afgri.com.au
87 Norseman Road
ESPERANCE WA

BANK DETAILS

Bank: NAB
Branch: PERTH
BSB: 086006 Account No: 721315336
Account Name: AFGRI Equipment Australia

Part of the AFGRI Group of Companies

